## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT.

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

## **BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

OIL CONS. DIV DIST. 3

NOV 0 1 2012

							MOA O T SOIS			
Date of Test	6/14/12	Opera	tor <u>Dugan</u>	Dugan Production Corp.		API #	30-045-32988			
Property Name	PA	TRIOT	Well No.	94S	_Location: Unit	D	Section	29 Township	26N Rang	ge <u>13W</u>
Well Status(Sh	ut-In of Produc	ng) Initia	I PSI: Tubing	105	Intermediate	114	Casing	7	Bradenhead	Ø
	*				<del> </del>					
OPEN BRAI		ND INTE	ERMEDIATE <sup>-</sup>	ГО АТМС	SPHERE INDI	VIDUAL	LY FOR	15 MINUTÈS	EACH	
	Bradenhead Interm					FLOW CHARACTERISTICS				
TÍMÉ	BH _ Int _ Cs	sg Int	Csg			BRADI	ENHEAD	INTERME	DIATE	
5 mintues	0	1		Steady Flov	v					
10 minutes	0 -	1		Surges						
15 minutes	Q	1		Down to No	othina					
20 minutes	0 7	,	***************************************	Nothing				· · · · · ·	•	
25 minutes	0 -			Gas					<del></del>	
30 minutes	0, _	1		Gas & Wate	er					
	1,			Watèr						
						· <u>-</u>			·	
If bradenh	ead flowed	d water,	check all o	f the des	scriptions th	at appl	y below	<u>/:</u>		
	·							_		
	CLE	AR	FRESH		SALTY	SULFU	JR	BLACK	-	
5 MINUTE S	SHUT-IN	BRAD	ENHEAD .	0	_ INTER	RMEDIAT	E			
REMARKS										
* *	<u> </u>			·				· · · · · · · · · · · · · · · · · · ·	· ·	
<u> </u>			<u> </u>						•	
** *	<u> </u>									
						•		<del></del>		
Ву	A.lo	10 B	Duxac	O	Witne	ss				
	, ,	Swite	•							
		(Positi	on)		<del></del>					