

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3district.htm>

**BRADENHEAD TEST REPORT**  
(Submit 1 copy to above address)

**OIL CONS. DIV DIST. 3**

**NOV 01 2012**

Date of Test 11/6/12 Operator Dugan Production Corp. API # 30-045-29659  
Property Name MCCARTNEY Well No 1 Location: Unit A Section 2 Township 22N Range 09W  
Well Status (Shut-In or Producing) Initial PSI: Tubing Ø Intermediate Ø Casing Ø Bradenhead Ø

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

**PRESSURE**

**FLOW CHARACTERISTICS**

TIME	Bradenhead			Interm				FLOW CHARACTERISTICS	
	BH	Int	Csg	Int	Csg			BRADENHEAD	INTERMEDIATE
5 minutes	Ø		Ø				Steady Flow		
10 minutes	Ø		Ø				Surges		
15 minutes	Ø		Ø				Down to Nothing		
20 minutes	Ø		Ø				Nothing	X	
25 minutes	Ø		Ø				Gas		
30 minutes	Ø		Ø				Gas & Water		
							Water		


**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

**5 MINUTE SHUT-IN** BRADENHEAD Ø INTERMEDIATE \_\_\_\_\_

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By  Witness \_\_\_\_\_  
Switcher  
(Position)