

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

[http://emr.state.nm.us/ocd/District III/3district.htm](http://emr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT
(Submit 1 copy to above address)

OIL CONS. DIV DIST. 3

NOV 01 2012

Date of Test 5-24-12 Operator Dugan Production Corp. API # 30-045-30246
Property Name MAYRE Well No 90R Location: Unit N Section 31 Township 30N Range 14W
Well Status(Shut-In or Producing) Initial PSI: Tubing 4 Intermediate NA Casing 8 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	0	NA	8	NA	NA	
10 minutes	1		1			
15 minutes	1		1			
20 minutes	1		1			
25 minutes	1		1			
30 minutes	1		1			

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

FLOW CHARACTERISTICS

BRADENHEAD	INTERMEDIATE
0	NA

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

By

Jimmy Fine

Switcher

(Position)

Witness _____