

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

<http://emrdd.state.nm.us/ocd/DistrictIII/3distinc.htm>

**BRADENHEAD TEST REPORT**  
(Submit 1 copy to above address)

**OIL CONS. DIV DIST. 3**

**NOV 01 2012**

Date of Test 5-22-12 Operator Dugan Production Corp. API # 30-045-30930  
Property Name MOLLY PITCHER Well No 90 Location: Unit G Section 14 Township 30N Range 14W  
Well Status(Shut-In or Producing) Initial PSI: Tubing 22 Intermediate 0 Casing 17 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	0	0	17	0	0	
10 minutes	0		17			
15 minutes	0		17			
20 minutes	0		17			
25 minutes	0		17			
30 minutes	0		17			

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

FLOW CHARACTERISTICS

BRADENHEAD

INTERMEDIATE

BRADENHEAD	INTERMEDIATE

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

**5 MINUTE SHUT-IN**

BRADENHEAD

0

INTERMEDIATE

REMARKS:

By

Harry Smouse

Witness

Switcher

(Position)