

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT
(Submit 1 copy to above address)

OIL CONS. DIV DIST. 3

NOV 01 2012

Date of Test 5-24-12 Operator Dugan Production Corp. API # 30-045-31731
Property Name MAYRE Well No. 90S Location: Unit I Section 31 Township 30N Range 14W
Well Status(Shut-In or Producing) Initial PSI. Tubing 4 Intermediate NA Casing 9 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

		PRESSURE							FLOW CHARACTERISTICS	
		Bradenhead			Interm				BRADENHEAD	INTERMEDIATE
TIME		BH	Int	Csg	Int	Csg				
5 minutes		0	NA	9	NA	NA				
10 minutes										
15 minutes										
20 minutes									0	NA
25 minutes										
30 minutes										

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

By

Jimmy Fare

Switcher

(Position)

Witness