NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

OIL CONS. DIV DIST. 3

Date of Test <u>S-Z3-12</u> Operator			Dugan Production Corp.			API #	NOV 0 1 2012 30-045-31767		
Property Name	MUDDY MUI	DDY COM	Well No_	90	Location: Uni	t <u>F</u>	_Section	21 Township	24N Range 9W
Well Status(Sho	ut-In of Producing)	Initial PSI:	Tubing _	15	Intermedia <u>te</u>	AA .	_ Casing	35	Bradenhead 🥳
TIME 5 mintues 10 minutes 15 minutes 20 minutes 25 minutes 30 minutes	PRESSIBradenhead BH Int Csg O 35 O	URE Interm Int Csg	S S C N G	Steady Flow Gurges Down to Noth Nothing Gas Gas & Water Vater	ning	FLOW	CHARAC	INTERMEI	
								_	
5 MINUTE S REMARKS:		BRADENHEAI		*		ERMEDIAT	·		
Ву	Mike	Switcher (Position))		Wit	ness			