

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

**BRADENHEAD TEST REPORT**  
(Submit 1 copy to above address)

**OIL CONS. DIV DIST. 3**

**NOV 01 2012**

Date of Test 7/6/12 Operator Dugan Production Corp. API # 30-045-33684  
Property Name MORRISON SWD Well No 2 Location: Unit H Section 13 Township 22N Range 09W  
Well Status(Shut-In or Producing) Initial PSI: Tubing 2 Intermediate \_\_\_\_\_ Casing 3 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

**PRESSURE**

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	0		3			
10 minutes	0		3			
15 minutes	0		3			
20 minutes	0		3			
25 minutes	0		3			
30 minutes	0		3			

Steady Flow  
Surges  
Down to Nothing  
Nothing  
Gas  
Gas & Water  
Water

**FLOW CHARACTERISTICS**

**BRADENHEAD INTERMEDIATE**

BRADENHEAD	INTERMEDIATE
X	

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_ **OIL CONS. DIV DIST. 3**

**5 MINUTE SHUT-IN**


BRADENHEAD 0

INTERMEDIATE \_\_\_\_\_

**NOV 01 2012**

REMARKS:

By



Switcher  
(Position)

Witness