

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3district.htm>

**BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

**RCVD NOV 6 '12  
OIL CONS. DIV.**

**DIST. 3**

Date of Test 11-1-12 Operator Dugan Production Corp. API # 30-045-35148  
Property Name LENNON COM Well No 2 Location: Unit I Section 19 Township 22N Range 08W  
Well Status(Shut-In or Producing) (Shut-In) Initial PSI 0 Tubing 0 Intermediate 0 Casing 40 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

**PRESSURE**

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	0		40			
10 minutes	0		40			
15 minutes	0		40			
20 minutes	0		40			
25 minutes						
30 minutes						

**FLOW CHARACTERISTICS**

	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	X	
Gas		
Gas & Water		
Water		

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

**5 MINUTE SHUT-IN** BRADENHEAD 0 INTERMEDIATE \_\_\_\_\_

REMARKS:

By

*Kelly C. Smith*

Switcher

(Position)

Witness