

NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/District lil/3distric.htm

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Property Na	ame <u>NATANI</u>		32 Location: Unit 6		
Well Status	(Shut-In or Producing	Tubing 48	Intermediate Casi	ing 75 Brandenh	nead_ <u>0</u>
OPEN BI	RADENHEAD AND IN	TERMEDIATE	TO ATMOSPHERE INDI	VIDUALLY FOR 15	MINUTES EACH
TIME	PRESSURES: INTERMEDIATE	CASING		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes			Steady Flow		
10 minutes_		·	Surges		
15 minutes_	1/		Down to Nothin	ng	
20 minutes_			Nothing	✓	
25 minutes_			Gas		
30 minutes_			Gas & Water_		
			Water		
If bradenhe	ad flowed water, check a	ll of the descriptio	ns that apply below:		
CLI	EAR FRESH	SALTY	SULFUR BLA	CK CK	520 21 22 23
5 MINUTE REMARKS:	,	EAD	INTERMEDIATE		No. 30 By
				· Co	1
					9.5. Take
By Ge	orge arago	Wit	ness		
Pun	sition)				