

NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test_Och	ober 28, 63	Operator	Benson - Montin - Green	_ API #30-0 <u>39</u> -	05238
			Location: Unit <u>—</u>		
Well Status(Shut-In or Producing) Tubing 0 Intermediate Casing 0 Brandenhead 0					
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH					
_	RESSURES: ERMEDIATE	CASING		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes			Steady Flow		
10 minutes			Surges		
15 minutes	~		Down to Nothin	ng	V
20 minutes			Nothing		
25 minutes			Gas		
30 minutes			Gas & Water_		
			Water		1 20 21 22 23
If bradenhead flowed water, check all of the descriptions that apply below:					
CLEAR_	FRESH	SALTY	SULFUR BLA	CK	CONCENTS E
					or on 3
5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE					
REMARKS:					
By Alanzo H	ONY	Wit	ness		
(Position)		·			