

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

**BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test 6/4/03 Operator Dugan Production Corp. API # 30-045-05618  
Property Name WEST BISTI UNIT Well No. 156 Location: Unit J Section 36 Township 26N Range 13W  
Well Status(Shut-In or Producing) Tubing 0 Intermediate \_\_\_\_\_ Casing 20 lbs Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	INTERMEDIATE	CASING		FLOWED	FLOWED
5 minutes	<u>0</u>		Steady Flow		
10 minutes			Surges		
15 minutes			Down to Nothing		
20 minutes			Nothing	<u>X</u>	
25 minutes			Gas		
30 minutes	<u>0</u>		Gas & Water		
			Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_


**5 MINUTE SHUT-IN**

BRADENHEAD \_\_\_\_\_

INTERMEDIATE \_\_\_\_\_

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



By \_\_\_\_\_  
44 Switcher  
(Position)

Witness \_\_\_\_\_