

## BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7-16-03 Operator ROBERT L. BAYLESS API #30-0 45-05756  
Property Name NAVAJO TRIBAL SWD N Well No. 2 Location: Unit G Section 20 Township 26N Range 18W  
Well Status (Shut-In or Producing) \_\_\_\_\_ Tubing 0 Intermediate 0 Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	INTERMEDIATE	CASING		FLOWED	FLOWED
5 minutes	<u>0</u>	<u>0</u>	Steady Flow		
10 minutes	<u>0</u>	<u>0</u>	Surges		
15 minutes	<u>0</u>	<u>0</u>	Down to Nothing		
20 minutes			Nothing	<u>X</u>	<u>X</u>
25 minutes			Gas		
30 minutes			Gas & Water		
			Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By William Schneider Witness \_\_\_\_\_  
Pumper

(Position)