OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410

(505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/DistrictIII/3distric.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test	7-16-03	Operator R	OBERT L. BAYLESS	API #30-0	45-21497	
Property Name	NAVAJO TRI	BAL U Well No.	26 Location: Unit	Section 22	_Township2	6N Range 18W
Well Status (Shut-In or Producing) Tubing 90 Intermediate 0 Casing 90 Brandenhead 0						
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH						
TIME	PRESSURES: INTERMEDIATE	CASING			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes	0	40	Steady Flow			
10 minutes		90	Surges			
15 minutes	O	90	Down to Nothing			
20 minutes	0	90	Nothing	~	4	\times
25 minutes	0	90	Gas			
30 minutes	0	90	Gas & Water			78/29/30/20
			Water			00, 50 50
If bradenhead flowed water, check all of the descriptions that apply below:						400
CLEAR	FRESH	SALTY	SULFUR	BLACK		Commence of the commence of th
5 MINUTE SHUT-IN BRADENDHEAD O INTERMEDIATE						
REMARKS:						
By <u></u> <u> </u>	william Schn	eidet,	Witness			
	(Positie	on)				