NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3district.htm

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 12 May 03 Operator MERRION OIL & GAS CORP. API #30-0 45-05780

Property Name BLACKROCK C Well No. 1 Location: Unit C Section 21 Township 26N Range 11W

Well Status(Shut-In or Producing) Tubing 322 Intermediate ____ Casing 1 Brandenhead 5

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES: INTERMEDIATE	CASING
5 minutes		1
10 minutes		↓
15 minutes		↓
20 minutes		↓
25 minutes		↓
~~30 minutes~~		

	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
Steady Flow		
Surges		
Down to Nothing	X	
Nothing		
Gas	X	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR_____ FRESH_____ SALTY_____ SULFUR_____ BLACK

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE_____

REMARKS: Blew down in 10 seconds, Packer in hole

By Michael Coley

Contract Pumper
(Position)

Witness_____

MAY 2003