

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505) 334-6178 Fax (505) 334-6170

BRADENHEAD TEST REPORT  
(Submit 2 copies to above address)

Date of Test 6/9/03 Operator SG Interests I Ltd API #30-045-29151-00  
Property Name WEST BISTI 26-12-5 Well No. 2 Location: Unit K Section 5 Township 26N Range 12W  
Pressure (Shut-in or Producing) Tubing 73 psi. Intermediate N/A Casing 2 psi. Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING			
5 Minutes	<u>N/A</u>	<u>2 psi.</u>	Steady Flow	<u>0</u>	<u>N/A</u>
10 Minutes	<u>↓</u>	<u>/</u>	Surges	<u>/</u>	<u>↓</u>
15 Minutes	<u>↓</u>	<u>/</u>	Down to Nothing	<u>/</u>	<u>↓</u>
20 Minutes	<u>↓</u>	<u>/</u>	<u>Nothing</u>	<u>/</u>	<u>↓</u>
25 Minutes	<u>/</u>	<u>/</u>	Gas	<u>/</u>	<u>/</u>
30 Minutes	<u>/</u>	<u>/</u>	Gas & Water	<u>/</u>	<u>/</u>
			Water	<u>/</u>	<u>/</u>

If Bradenhead flowed water, check all of the descriptions that apply below:

CLEAR / FRESH / SALTY / SULFUR / BLACK /

REMARKS:

No gas present.



By B. McKinney 6/9/03 Witness /  
Position Production