

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FORM APPROVED  
OMB No. 1004-0135  
Expires November 30, 2000

**SUNDRY NOTICES AND REPORTS ON WELLS**  
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.*

**SUBMIT IN TRIPLICATE - Other instructions on reverse side**

1. Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other		5. Lease Serial No. <b>NMSF077085</b>
2. Name of Operator <b>ConocoPhillips Co.</b>		6. If Indian, Allottee or Tribe Name
3a. Address <b>P.O. Box 2197, WL3-6081 Houston Tx 77252</b>	3b. Phone No. (include area code) <b>(832)486-2463</b>	7. If Unit or CA/Agreement, Name and/or No.
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) <b>Sec. 35 T28N R10W SWNE 1525FNL 1650FEL</b>		8. Well Name and No. <b>Omler A #2</b>
		9. API Well No. <b>30-045-11680</b>
		10. Field and Pool, or Exploratory Area <b>Basin Dakota</b>
		11. County or Parish, State <b>San Juan NM</b>

**12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA**

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/ Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other <b>Clean Out &amp; Tubing Chg</b>
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

This well was cleaned out & tubing changed. 2.375" tubing now lands @ 6416'. Daily Summary is attached.



ACCEPTED FOR RECORD

MAY 10 2005

FARMINGTON FIELD OFFICE  
BY *[Signature]*

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) <b>Christina Gustartis</b>		Title <b>As Agent for ConocoPhillips Co</b>
Signature <i>Chris Gustartis</i>		Date <b>04/26/2005</b>

**THIS SPACE FOR FEDERAL OR STATE OFFICE USE**

Approved by	Title	Date
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		
Office		

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on reverse)

NMOCD

# Regulatory Summary

## OMLER A 2

Clean-out, 04/01/2005 00:00

API/UWI	County	State/Province	Surface Legal Location	N/S Dist (ft)	N/S Ref	E/W Dist (ft)	E/W Ref
300451168000	SAN JUAN	NEW MEXICO	NMPM-28N-10W-35-G	1,525.0	N	1,650.0	E
Ground Elevation (ft)	Latitude (DMS)	Longitude (DMS)	Spud Date	Rig Release Date			
5,838.00	36° 37' 18.012" N	107° 51' 39.96" W	07/03/1965	07/21/1965			

04/01/2005 07:00 - 04/01/2005 17:00

### Last 24hr Summary

CONOCOPHILLIPS SAFETY MEETING, SAFETY MEETING, MOVE IN AND RIG UP EQUIPMENT & RIG, BLOW WELL DOWN, ND WELL HEAD, NU BOP, TEST BOP, PULL AND REMOVE HANGER, INSTALL STRIPPER RUBBER, SECURE LOCATION AND SHUT DOWN.

04/04/2005 07:00 - 04/04/2005 17:30

### Last 24hr Summary

SAFETY MEETING, BLOW WELL DOWN, TALLY OUT WITH 2 1/16 TBG. LAYING DOWN 6226', MOVE OUT TRAILER WITH 2 1/16 TBG, MOVE IN 2 3/8 TBG. & COLLARS, PICK UP & RUN IN WITH 3 7/8 SWEDGE, ONE DRILL COLLAR, BUMPER SUB, JARS, 5 DRILL COLLARS, INTENSIFIER, X-OVER ON 2 3/8 TBG. TO 5797', SHUT DOWN & SECURE LOCATION DUE TO WIND CONDITIONS.

04/05/2005 07:00 - 04/05/2005 15:00

### Last 24hr Summary

KEY SAFETY MEETING, LOCATION SAFETY MEETING, BLOW WELL DOWN, TAG TIGHT SPOT @ 6192', RIG UP POWER SWIVEL, WORK SWEDGE IN TIGHT AREA & PUSH DOWN TO 6245 WITH SWEDGE, HANG POWER SWIVEL BACK, PULL 1850' OF TBG., SHUT DOWN DUE TO WIND CONDITIONS.

04/06/2005 07:00 - 04/06/2005 18:30

### Last 24hr Summary

SAFETY MEETING, BLOW WELL DOWN, PULL OUT WITH SWEDGE, PULL OUT WITH REMAINS OF MILL SHOE LEFT IN THE HOLE IN 1966 ON THE SWEDGE, ALSO SIGNS OF OTHER JUNK UP IN THE MILL SHOE, HAD 10 JTS. OF 2 3/8 TBG. BENT FROM WORKING THE SWEDGE, RUN BACK IN WITH 3 7/8 JUNK MILL, JARS & COLLARS ON 2 3/8 TBG., STOP @ 4026' AND UNLOAD THE WELL WITH AIR, RUN IN WITH JUNK MILL & TAG @ 6245', SAW NO INDICATION OF TIGHT SPOT, RIG UP POWER SWIVEL, BREAK CIRCULATION WITH AIR MIST, AIR OF 1200 CFM, MIST OF 12 BPH FLUID, 1.5 GBH OF FOAMER, DRILLED FROM 6245' TO 6247' (THROUGH MODEL D) RUN ON DOWN AND TAG @ 6412', BREAK CIRCULATION AND CLEAN OUT TO 6415', GETTING BACK IRON/METAL, SWEEP CLEAN, HANG SWIVEL BACK, PULL ABOVE PERFS TO 6191', SECURE LOCATION AND SHUT DOWN.

04/07/2005 07:00 - 04/07/2005 17:30

### Last 24hr Summary

SAFETY MEETING, BLOW WELL DOWN, RUN IN AND TAG FILL @ 6414', BREAK CIRCULATION WITH AIR MIST, AIR OF 1200 CFM, MIST OF 12 BPH FLUID, 1.5 GPH FOAMER, DRILL & CLEAN OUT TO PBTD @ 6471', CIRCULATE CLEAN, GOOD SAND & JUNK RETURNS, PULL UP ABOVE PERFS @ 6191' SECURE LOCATION AND SHUT DOWN.

04/08/2005 07:00 - 04/08/2005 17:30

### Last 24hr Summary

BLOW WELL DOWN - Pooh w/tbg., collars, jars & mill - SECURE LOC/SHUT DOWN/WIND CONDITIONS

04/11/2005 07:00 - 04/11/2005 17:00

### Last 24hr Summary

SAFETY MEETING, BLOW WELL DOWN, RUN IN WITH .80 X 2 3/8 EXPENDABLE CHECK WITH MULE SHOE BOTTOM, 1.10 X 1.78 F-NIPPLE, 204 JTS. OF 2 3/8 TBG., LAND TBG. @ 6416', RIG DOWN FLOOR, ND BOP, NU WELL HEAD, PUMP EXPENDABLE CHECK, RIG DOWN RIG AND EQUIPMENT, SECURE LOCATION & MOVE.