

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

**BRADENHEAD TEST REPORT**  
(Submit 2 copies to above address)

Date of Test 5-14-03 Operator Dugan Production Corp. API # 30-045-25164  
Property Name LAVA FALLS Well No. 1 Location: Unit J Section 27 Township 24N Range 08W  
Well Status(Shut-In or Producing) Tubing 19 Intermediate \_\_\_\_\_ Casing 19 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	INTERMEDIATE	CASING		FLOWED	FLOWED
5 minutes		<u>19</u>	Steady Flow	<u>0</u>	
10 minutes		<u>19</u>	Surges	<u>0</u>	
15 minutes		<u>19</u>	Down to Nothing	<u>0</u>	
20 minutes			Nothing		
25 minutes			Gas		
30 minutes			Gas & Water		
			Water		

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

**5 MINUTE SHUT-IN**

BRADENHEAD

T.L.T.m

INTERMEDIATE \_\_\_\_\_

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By

C.E. Harris #49

Witness \_\_\_\_\_

49

Switcher  
(Position)

