NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District111/3distric.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6-25-03 Operator ROBERT L. BAYLESS, PRODUCER LLC API #30-0 45-28369						
Property Name	MARRON WI	N FED Well No.	S Location: Unit _	H Section 2	3 Township 2	7N Range 8W
Well Status (Sho	ut-In or Producing)	Tubing //	6 Intermediate NA	Casing //8	Brandenhead	<u> </u>
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH						
TIME	PRESSURES: INTERMEDIATE	CASING		-	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes	NA	118	Steady Flow		lothing	NA
10 minutes			Surges		\rightarrow	
15 minutes	/		Down to Nothing			
20 minutes			Nothing			
25 minutes			Gas	· · · · · · · · · · · · · · · · · · ·	N.	
30 minutes			Gas & Water		25.651,185	2303
			Water		407	53 53 S
If bradenhead flowed water, check all of the descriptions that apply below:						
CLEAR FRESH SALTY SULFUR BLACK						
CLEAR FRESH SALTY SULFUR BLACK 5 MINUTE SHUT-IN BRADENDHEAD INTERMEDIATE						
REMARKS:						
Ву	David 3	lmeon wi	itness			
	Pumpe	w	CHOS	***************************************		a support de la
	/ (Positio	on)				