OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://cmnrd.state.nm.us/ocd/District111/3distric.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

| Date of Test 8-20-03 Operator ROBERT L. BAYLESS, PRODUCER LLC API #30-0 45-28446 | | | | | |
|---|----------------------------|---------------------------------------|------------------|----------------------|------------------------|
| Property Name | MARRON WN F | ED COM Well No. 9 | Location: Unit H | Section27Township | 27N Range 8W |
| Well Status (Shut-In) or Producing) Tubing 21 Intermediate NA Casing 558 Brandenhead / | | | | | |
| OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH | | | | | |
| TIME | PRESSURES: INTERMEDIATE | CASING | | BRADENHEAD FLOWED | INTERMEDIATE FLOWED |
| 5 minutes | NA | 538 | Steady Flow | Nothing | NA |
| 10 minutes | | 558 | Surges | | |
| 15 minutes | | 558 | Down to Nothing | | |
| 20 minutes | | | Nothing | | |
| 25 minutes | | · · · · · · · · · · · · · · · · · · · | Gas | | |
| 30 minutes | | | Gas & Water | | 28 29 30 37 |
| | | | Water | | 00.5. |
| If bradenhead flowed water, check all of the descriptions that apply below: | | | | | |
| CLEAR FRESH SALTY SULFUR BLACK | | | | | |
| 5 MINUTE SHUT-IN BRADENDHEAD INTERMEDIATE NA | | | | | |
| 1-PSI, blew down to Nothing - in 5 seconds - No Flow | | | | | |
| | | | | | |
| Ву | Davel Hr | ver Wit | tness | | |
| | Daved HA Pumper | | | | |
| | (Positio | on) | | | |