

NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District @/3distric.htm

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

| Date of Test 11-17-03 | Operate | OF FOUR STAR OIL & GAS | API #30-0 <u>45-2</u> | 22673 |
|--|-------------|------------------------|-----------------------|------------------------|
| Property Name John CHARLES | Well No | 7A Location: Unit C S | Section_13_Towns | hip27N Range 9W |
| Well Status(Shut-In or Producing | Tubing 31 | Intermediate N/A Casi | ng 44 Branden | head <u>34</u> |
| OPEN BRADENHEAD AND IN | NTERMEDIATE | TO ATMOSPHERE INDIV | VIDUALLY FOR 15 | MINUTES EACH |
| PRESSURES: TIME INTERMEDIATE | CASING | - | BRADENHEAD FLOWED | INTERMEDIATE FLOWED |
| 5 minutes | 44 | Steady Flow | | |
| 10 minutes | 43 | Surges | · | |
| 15 minutes | 43 | | g | |
| 20 minutes | 44 | Nothing | | |
| 25 minutes_ | 45 | Gas | | |
| 30 minutes | 46 | Gas & Water | | 2021222 |
| | | Water | X | |
| If bradenhead flowed water, check all of the descriptions that apply below: | | | | |
| CLEAR_X FRESH SALTY SULFUR BLACK | | | | |
| 5 MINUTE SHUT-IN BRADENHEAD 10 INTERMEDIATE | | | | |
| REMARKS: Bradenhead blew down in I second in a puff through I inch ball valve. | | | | |
| After a few seconds clear water started to flow. Flow continuously | | | | |
| approximately 3 gallons per minute. | | | | |
| By My Beat | | tness | | |
| Operation Technician (Position) | | | | |