OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170

http://emnrd.state.nm.us/ocd/DistrictIII/3distric.htm

## **BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test	of Test 6-10-03 Operator KUKUI OPERATING			API #30-0 45-27741		
Property Name	ANGEL PEAK 11A		Location: Unit A			<b>~</b>
Pressure (Shut-l	In or Producing	Tubing 5	Intermediate	Casing	_Bradenhead	<i>D</i>
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH						
TIME	PRESSURES: INTERMEDIATE	CASING		В	RADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes		15	Steady Flow			
10 minutes			Surges			
15 minutes			Down to Nothing			
20 minutes	<del></del>		Nothing			
25 minutes			Gas			
30 minutes		15	Gas & Water			
			Water			3 29 29 70 3
If bradenhead	flowed water, check all	of the descriptions that ap	<u>ply below:</u>		A COLO	(((0.0.3)))
CLEAR _	FRESH _	SALTY	SULFUR	BLACK		JUN 2003 RECEIVED OF
5 MIN REMARKS:	UTE SHUT-IN	BRADENHEAD	INTERMEDIATE			State of the state
By E	ERIC SMITH	W	itness .			
_	Pumper					

(Position)