

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

**BRADENHEAD TEST REPORT**  
(Submit 2 copies to above address)

Date of Test 5-5-05 Operator Dugan Production Corp. API # 3004508042  
Property Name Mae Gale Com Well No. 1 Location: Unit E Section 24 Township 29N Range 11W  
Well Status(Shut-In or Producing) \_\_\_\_\_ Tubing 180 Intermediate N/A Casing 660 Bradenhead 30

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	INTERMEDIATE	CASING		FLOWED	FLOWED
5 minutes			Steady Flow		
10 minutes			Surges		
15 minutes			Down to Nothing		
20 minutes			Nothing		
25 minutes			Gas		
30 minutes			Gas & Water		
			Water		

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR ☒ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

**5 MINUTE SHUT-IN** BRADENHEAD 0 INTERMEDIATE N/A

REMARKS:

Down to nothing within 30 sec less than 1/2 gallon of H<sub>2</sub>O.

By Chris Zuccato  
72 Switcher  
(Position)

Witness \_\_\_\_\_

