

## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District II//3distric...tm

## **BRADENHEAD TEST REPORT**

(submit 2 copies to above address)

Date of Test 06-19.03	Operator	r Dominion/E	<u>,' P</u> API #3	0-0 <u>45-0</u>	6740
Property Name Mudge 'A'		L			
Well Status(Shut-In or Producing	Tubing O	Intermediate	Casing 10	Brandenhe	ad_ <u>O</u> _
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH					
PRESSURES: TIME INTERMEDIATE	CASING		BRADE FLOW	NHEAD ED	INTERMEDIATE FLOWED
5 minutes		Steady Flo	w		
10 minutes		Surges			
15 minutes		Down to Nothing			···
20 minutes		Nothing			
25 minutes		Gas			
30 minutes_	Gas & Water				
		Water			
If bradenhead flowed water, check all of the descriptions that apply below:					
CLEAR FRESH SALTY SULFUR BLACK					
5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE REMARKS:					
REMARKS:					
Well ON PUMP; COMPRESSION					
	<del></del>				
By Dich Scan lan	Witn	ness			
Pum PER (Position)	<del></del>				