



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrnr.state.nm.us/ocd/District III/3distric.htm](http://emrnr.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 6/11/03 Operator Koch Exploration Co, LLC API #30-0 45-26002
Property Name Dryden Well No. 2E Location: Unit 1 Section 22 Township 28N Range 8W
Well Status (Shut-In or Producing) Tubing 310 Intermediate 12 Casing 311 Bradenhead TSTM

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes	<u>0</u>	<u>311</u>	Steady Flow	
10 minutes	<u>0</u>	<u>311</u>	Surges	
15 minutes	<u>0</u>	<u>311</u>	Down to Nothing ☒	☒
20 minutes	<u>()</u>	<u>()</u>	Nothing	
25 minutes	<u>()</u>	<u>()</u>	Gas	
30 minutes	<u>()</u>	<u>()</u>	Gas & Water	
			Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE 0

REMARKS: Int down to nothing in 3sec. Bradenhead pressure was too low
to measure.

By Glenn R Hise
contract pumpin
(Position)

Witness _____

