NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division Aztec District Office 1000 Rio Brazos Road Aztec, NM 87410 (505)334-6178 FAX:(505)334-6170

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 4-30-03 Operator			Dugan Production Corp.		API#	30-045-	29455			_	
	BENGAL C							ownship	27N	_ Range	<u>13W</u>
Well Status(Shut-In Producing Tubing			.27 Intermediate		Casing	Casing 26		Bradenhead		0	
	OPEN BRADI	ENHEAD A	ND INTE	RMEDIATE TO A	ΓMOSPHERE	INDIVII	DUALLY	FOR 1	15 MIN	UTES E	EACH
	PRESSURES:				BRADE	ENHEAD	IŅ	ITERMEI	DIATE		
TIME	INTERMEDIATE	CASING	-		FLOW	ED	F	LOWED		_	
5 mintues		26	_ s	teady Flow				. الما المالية		_	
10 minutes		26	_ s	urges			/	56/	8.97		
15 minutes		26	D	own to Nothing		·			3		
20 minutes			_ N	othing			10 -	MAY 2	003		
25 minutes				as			₩ 1 c			: 65	
30 minutes			– G	as & Water			100	ناريا	્ર. ગ		
00 1111111100		<u> </u>		/ater			10	75°C7 - 500	7777		
				. —				المناهد	منتقب الم	2	
<u>If bradenh</u>	ead flowed w	ater, che	ck all of	the description	ns that appi	y belov	<u>v:</u>				
	CLEAR		FRESH_	SALTY	SULFL	IR	BLACK_		_		
5 MINUTE S	SHUT-IN	BRADENHE	AD		INTERMEDIATI	Ē					
REMARKS:								•			
							· · · · · · · · · · · · · · · · · · ·			-	
						·				-	
											
										_	
_	A STATE OF THE PARTY OF THE PAR	(In									
Ву	JI BIC		<u> </u>	erg -	Witness					_	
30		Switcher (Position)									