OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District M/3distric.htm

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 7-14-03	Operator	FOUR STAR OIL & GAS	API #30-0 45-2	23676
Property Name Mexico Feberal				
Well Status(Shut-In or Producin	g Tubing 35	Intermediate NA Casi	ng 65 Brandenl	head <u>O</u>
OPEN BRADENHEAD AND I	NTERMEDIATE	TO ATMOSPHERE INDIV	VIDUALLY FOR 15	MINUTES EACH
PRESSURES: TIME INTERMEDIATE	CASING		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes	63	Steady Flow		
10 minutes	58	Surges		
15 minutes	46	Down to Nothin	g	
20 minutes		Nothing	X	
25 minutes		Gas		
30 minutes		Gas & Water		
		Water		20 71 77 22 22
If bradenhead flowed water, check all of the descriptions that apply below:				
CLEAR FRESH	SALTY	SULFUR BLAC	CK Story	DEC 2003
5 MINUTE SHUT-IN BRADENHEAD O INTERMEDIATE				
REMARKS:				
	-			
By Am But	Witn	iess		
Operation Technician (Position)				