OH. CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(305) 334-6178 FAX: (505) 334-6170
http://emard.state.nm.us/ocd/District.lli/3distric.htm

## BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test	6-11-03 Operat	or <b>ROB</b>	ERT L. BAYLESS	APT#30-0	45-26130	
Property Name	T L RHODES B DK & PO	G Well No. 1E	Location: Unit <u>M</u>	Section 20	_ <b>To</b> wnship2	8N Range 11W
Well Status (Shut-In or Producing)  Tubing 120 Intermediate Casing 25 Brandenhead SPST						
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH						
TIME	PRESSURES: INTERMEDIATE	CASING			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes			Steady Flow			
10 minutes			Surges	<u> </u>		
15 minutes			Down to Nothing	Blew strigh	Han	
20 minutes			Nothing			
25 minutes			Gas			
30 minutes		,	Gas & Water		300	<u> </u>
	į		Water			(1)
If bradenhead t	flowed water, check all of the	descriptions that	apply below:			107 (1) (1) (1) (1) (1) (1) (1) (1) (1) (1)
CLEAR	FRESH	SALTY	SULFUR	BLACK	c	
5 MINUTE SH	UT-IN BRADENDHEAI	<b>.</b>	INTERMEDIATE	Wallet .	_	
REMARKS:  5 85 I Blow stright das						
Ву	West Man Carpon (Position)	Men. With	ess	3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3		