

### BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-21-03 Operator ROBERT L. BAYLESS API #30-0 45-29266

Property Name HORN CANYON FC & PC Well No. 1 Location: Unit D Section 15 Township 28N Range 11W

Well Status (Shut-In or Producing) \_\_\_\_\_ Tubing 8 Intermediate - Casing 15 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	INTERMEDIATE	CASING		FLOWED	FLOWED
5 minutes			Steady Flow		
10 minutes			Surges		
15 minutes			Down to Nothing		
20 minutes			Nothing	X	
25 minutes			Gas		
30 minutes			Gas & Water		
			Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN BRADENHEAD \_\_\_\_\_ INTERMEDIATE \_\_\_\_\_

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By

Albert Branda  
Pumper  
(Position)

Witness \_\_\_\_\_

