

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

BRADENHEAD TEST REPORT
(Submit 2 copies to above address)

Date of Test 4-30-03 Operator Dugan Production Corp. API # 30-045-07023
Property Name FULLERTON Well No. 1 Location: Unit F Section 34 Township 28N Range 13W
Well Status(Shut-In or Producing) Tubing 370 Intermediate — Casing 360 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	INTERMEDIATE	CASING		FLOWED	FLOWED
5 minutes	-	<u>360</u>	Steady Flow		
10 minutes	-	<u>360</u>	Surges		
15 minutes	-	<u>360</u>	Down to Nothing		
20 minutes	-		Nothing	✓	
25 minutes	-		Gas		
30 minutes	-		Gas & Water		
			Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD _____ INTERMEDIATE _____

REMARKS:

By WARD Wapenats
30 Switcher
(Position)

Witness _____