

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District ill/3distric.htm

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test_	7-7-03	Operator	Williams	_API #30-0_3 <i>9</i> 2	2 606 900
Property Name <u>Losa</u> Well No. 162 Location: Unit K Section 30 Township 31 MR ange 5 W					
Well Status (Shut-In or Producing) Tubing 151 Intermediate MA Casing 155 Brandenhead					
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH					
TIME _	PRESSURES: INTERMEDIATE	CASING		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes	NA	155	Steady Flow		NA
10 minutes			Surges		
15 minutes			Down to Nothing		
20 minutes			Nothing	0	,
25 minutes	·		Gas		
30 minutes			Gas & Water	3 9 10 11 72	
			Water	G NOV	
If bradenhead flowed water, check all of the descriptions that apply below:					
CLEAR FRESH SALTY SULFUR BLACK					
5 MINUTE SHUT-IN BRADENHEADINTERMEDIATE					
REMARKS:					
Braden head dead and dry					
By Shim Team (Position	y Brooks leader	Witne	ss		