

**NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT**

OIL CONSERVATION DIVISION  
Aztec District Office  
1000 Rio Brazos Road  
Aztec NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
[http://nemrnr.state.nm.us/ocd/District III/district.htm](http://nemrnr.state.nm.us/ocd/District%20III/district.htm)

**BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test 7-10-03 Operator CORDILLERA ENERGY, INC. API# 30-045-010293

Property Name TAFOYA Well No. 1A Location: Unit F Section 35 Twp 32N Range 13W

Pressure (Shut-in or Producing) Tubing 20 Intermediate N/A Casing 40 Bradenhead 30

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes		<u>40</u>	Steady Flow	
10 minutes		<u>40</u>	Surges	
15 minutes		<u>40</u>	<u>Down to Nothing</u> ✓	
20 minutes			Nothing	
25 minutes			<u>Gas</u> ✓	
30 minutes			Gas & Water	
			Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

REMARKS:

Bradenhead blew down immediately.

By Larry Bringham  
Pumper  
(Position)

Witness \_\_\_\_\_

