

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

BRADENHEAD TEST REPORT
(Submit 2 copies to above address)

Date of Test 5-14-03 Operator Dugan Production Corp. API # 30-045-10776
Property Name CUCCIA Well No. 1 Location: Unit G Section 14 Township 31N Range 13W
Well Status(Shut-In or Producing) Tubing 340 Intermediate _____ Casing 800 Bradenhead 151M

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	INTERMEDIATE	CASING		FLOWED	FLOWED
5 minutes	<u>0</u>	<u>800</u>	Steady Flow		
10 minutes			Surges		
15 minutes			Down to Nothing		
20 minutes			<u>Nothing</u>		
25 minutes			Gas		
30 minutes			Gas & Water		
			Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD _____ INTERMEDIATE _____

REMARKS:

By Blaine Allison Witness _____
Switcher
(Position)