

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
Aztec District Office
1000 Rio Brazos Road
Aztec NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://nemnrd.state.nm.us/ocd/District III/3district.htm](http://nemnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7-9-03 Operator CORDILLERA ENERGY, INC. API# 30-045-11081

Property Name LANDAUER Well No. 1 Location: Unit H Section 3 Twp 31N Range 13W

Pressure (Shut-in or Producing) Pressure Tubing 790 Intermediate N/A Casing 790 Bradenhead 10

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH


TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING			
5 minutes		<u>790</u>	Steady Flow		
10 minutes		<u>790</u>	Surges		
15 minutes		<u>790</u>	Down to Nothing	☒	
20 minutes			Nothing		
25 minutes			Gas	☒	
30 minutes			Gas & Water		
			Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

REMARKS:

Braden head blew down immediately.



By Larry Brigham
Pumper
(Position)

Witness _____