

**NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT**

OIL CONSERVATION DIVISION
Aztec District Office
1000 Rio Brazos Road
Aztec NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://nemnr.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7-7-03 Operator CORDILLERA ENERGY, INC. API# 30-045-23006

Property Name CHAVEZ COM Well No. 1A Location: Unit P Section 2 Twp 31N Range 13W

Pressure (Shut-in or Producing) _____ Tubing 43 Intermediate N/A Casing 43 Bradenhead 5

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes		<u>43</u>	Steady Flow	
10 minutes		<u>43</u>	Surges	
15 minutes		<u>43</u>	Down to Nothing	
20 minutes			Nothing	
25 minutes			<u>Gas</u> <u>5# to nothing</u>	
30 minutes			Gas & Water	
			Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

REMARKS:

Pressure on braden head bled off immediately

By Larry Bingham Witness _____

Pumper
(Position)

