



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III3district.htm](http://emnrd.state.nm.us/ocd/District%20III3district.htm)

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 12-12-03 Operator Pure Resources API #30-045-23196

Property Name Montoya 25-1 FC Well No. 25-1 FC Location: Unit H Section 25 Township 32N Range 13W

Well Status (Shut-In or Producing) Tubing 44 Intermediate N/A Casing 46 Bradenhead 0.0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes	<u>N/A</u>	<u>45</u>	Steady Flow	<u>N/A</u>
10 minutes		<u>46</u>	Surges	
15 minutes		<u>45</u>	Down to Nothing	
20 minutes			Nothing	
25 minutes			Gas	
30 minutes			Gas & Water	
			Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0.0 psi INTERMEDIATE _____

REMARKS:

Well is Pumping, therefore producing up both the tubing
and production casing.
Braden head showed no pressure or flow

By Russ Knight
Mrs. Tech.
(Position)

Witness _____

