(Position)

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410

(505) 334-6178 FAX: (505) 334-6170

http://emnrd.state.nm.us/ocd/DistrictIII/3distric.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test	7/9/03	Operator	ROBERT I	., BAYLESS, PRODU	CER LLC	API#30	0-0 <u>45-242</u>	142	······································
Property Name	SWD		Well No.	Location: Unit	P	Section_	7 Towns	hip <u>30</u>	N Range 12W
Well Status (Shi	ut-In or Producing)		Tubing <u>77</u>	Intermediate	Casi	ng <u>a</u>	Brandenhe	ad 🔍	
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH									
TIME	PRESSURES: INTERMEDIATE	<u>.</u>	CASING			******	BRADE! FLO	NHEAD WED	INTERMEDIATE FLOWED
5 minutes				Steady Flow		- , ,			
10 minutes			 	Surges					
15 minutes		<i>\to</i>	-	Down to Nothing	;	***************************************			······
20 minutes				Nothing					
25 minutes				Gas			2572	320 ¹ 31310	
30 minutes				Gas & Water			14. Co., (207	الله المالية
				Water				1003	<u> </u>
If bradenhead flowed water, check all of the descriptions that apply below: CLEAR FRESH SALTY SULFUR BLACK									
5 MINUTE SHUT-IN BRADENDHEAD INTERMEDIATE									
REMARKS:									
:	······································				· · · · · · · · · · · · · · · · · · ·				

By Palmarknepp Witness Pumpor									
tumpo-									