OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505) 334-6178 FAX: (505) 334-6170

http://emnrd.state.nm.us/ocd/DistrictIII/3distric.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test	7/ 103	Operator	ROBERT L. BAYI	LESS A	API #30-0	45-28993	72-79-00-10-79-10-00-10-10-10-10-10-10-10-10-10-10-10-	
Property Name	MOSEL1	EY Well N	To. 1 Location:	Unit <u>K</u> Sec	tion 2	Township	30N Range_	12W_
Well Status (St	nut-In or Producing) Tubin	g <u>-©</u> Intermedi	ate <u> </u>	ing 4	Brandenhead_	<u> </u>	
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH								
TIME	PRESSURES: INTERMEDIATI	E CASI	NG		В.	RADENHEAD FLOWED	INTERM FLOV	
5 minutes			Steady Flo	•w				
10 minutes			Surges	-				
15 minutes		4	Down to N	othing				
20 minutes			Nothing	***************************************	·····			····
25 minutes			Gas					
30 minutes			Gas & Wa	ter				
			Water					······
If bradenhead flowed water, check all of the descriptions that apply below:								
CLEAR	FRES	H SA	LTYSU	LFUR	_ BLACK			
5 MINUTE SHUT-IN BRADENDHEAD INTERMEDIATE								
REMARKS:	Jing NF	Casing	5					
By A	almon	•	Witness					
***************************************	Pumper							
	(Posit	ion)						