

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 3346170
http:\\emnrd.state.nm.us/ocdIDlstrict.ltU3distric.htm

## **BRADENHEAD TEST REPORT**

(submit 2 copies to above address)

Date of Test <u>8-12-03</u>		Operator McElvain Oil and Gas API #30-0 45-08854			
Property Name *So. Union		Well No.#1B	Location: Unit B	Section 3 To	wnship29 Range13
Well Status (Shu	nt-In or <u>Producir</u>	ng) Tubing 242	Intermediate	Casing 468 B	radenhead 15
OPEN BRADE	NHEAD AND IN	TERMEDIATE TO	O ATMOSPHERE INI	DIVIDUALLY FO	R 15 MINUTES EACH
TIME IN	PRESSURES:	CASING			INTERMEDIATE FLOWED
5 minutes		468	Steady Flow		
10 minutes		468			
15 minutes		1	Down to Nothing _		
20 minutes					- TTT 17 TT
				/sc	2003
			Water	25	0,000
If bradenhead flow	ved water, check a	all of the description	s that apply below:		
CLEAR FRESH SALT SULFUR BLACK					
5 MINUTE SHUT- REMARKS:	-IN BRADENF	HEAD	INTERMEDIATE		
* Vulnerable Area					
By Joe Elledge		Witnes	ss		
Production Foreman (Position)	ı				