

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District Ill/3distric.htm

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

	(55511117 2		•)	
Date of Test 10-29-03 Operator Maralet Resource PI #30-0 4528908				
Property Name Tak	Well No/_	Location: Unit <u>#</u>	Section_7 Townsh	ip <u>JAN</u> Range <u>13 w</u>
Well Status(Shut-In of Producing) Tubing Intermediate Casing / Brandenhead				
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH				
PRESSURES: TIME INTERMEDIATE	CASING		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes		Steady Flow_		
10 minutes		Surges		
15 minutes		Down to Nothing		
20 minutes		Nothing		
25 minutes Gas				
30 minutes		Gas & Water		
		Water		
If bradenhead flowed water, check all of the descriptions that apply below:				
CLEAR FRESH	SALTY	SULFURBL	ACK	
5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE				
REMARKS:				
	· · · · · · · · · · · · · · · · · · ·			
By Mart (m) Dodan Witness Witness				
Pumper (Position)				