



[http://enhrd.state.nm.us/ocd/District III3 distric.htm](http://enhrd.state.nm.us/ocd/District%20III3%20distric.htm)

(submit 2 copies to above address)

Date of Test 4-28-03 Operator DJ Simmons API #30-0 45 20030
Property Name Simmon Well No. E-4 Location: Unit _____ Section 23 Township 29^N Range 9^W
Well Status(Shut-In or Producing) _____ Tubing 72 Intermediate Casing 110 Brandenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURES:			BRADENHEAD	
TIME	INTERMEDIATE	CASING	FLOWED	INTERMEDIATE FLOWED
5 minutes			Steady Flow	
10 minutes			Surges	
15 minutes			Down to Nothing	
20 minutes			Nothing	X
25 minutes			Gas	
30 minutes			Gas & Water	
			Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE

REMARKS:

By R. Manchester
Field Tech.
(Position)

Witness _____

