

## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District ill/3distric.htm

## **BRADENHEAD TEST REPORT**

(submit 2 copies to above address)

Date of Test 6-27-0	Operator_	DJ Simon API #30-0 4	5 30649
Property Name Simmons Well No. 1 Location: Unit Section 25 Township 29 Range 9			
Well Status(Shut-In or Producing) Tubing 115 Intermediate 93 Casing 200 Brandenhead			
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH			
PRESSURES: TIME INTERMEDIATE	CASING	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes 93	200	Steady Flow	
10 minutes		Surges	
15 minutes		Down to Nothing	X
20 minutes		Nothing	1
25 minutes		Gas	X
30 minutes		Gas & Water	1 × 5 5
		WaterJAN	2003
If bradenhead flowed water, check all of the descriptions that apply below:			
CLEAR FRESH SALTY SULFUR BLACK			
5 MINUTE SHUT-IN BRADENHEAD O INTERMEDIATE 1 25.			
REMARKS: Bradenhead value full of cement			
Retest L new value			
		•	
By holland Witness_			
Position)			