



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/District.htm](http://emnr.state.nm.us/ocd/District%20III/District.htm)

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 09/04/03 Operator MERRION OIL & GAS CORP. API #30-0 45-30493

Property Name BARTENS PARK COM Well No. 1 Location: Unit I Section 36 Township 30N Range 13W

Well Status(Shut-In or Producing) Tubing 56 Intermediate Casing 56 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes		<u>56</u>	Steady Flow	
10 minutes			Surges	
15 minutes			Down to Nothing	
20 minutes			Nothing <input checked="" type="checkbox"/>	
25 minutes			Gas	
30 minutes			Gas & Water	
			Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE

REMARKS:

Bradenhead valve bad. Replaced valve

By Tim Merilatt
Contract Rumper
(Position)

Witness

