

NEW MEXICO ENERGY, MUNERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Well Status (Shut-In of Producing) Tubing 230 Intermediate 1/2 Casing 500 Brandenhead 0 OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH			
PRESSURES: INTERMEDIATE	CASING	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes	Steady Flow		
10 minutes	APR 2005 Surges		
15 minutes	O Down to No	thing	
20 minutes	Nothing Nothing	<u>k</u>	
25 minutes	The second secon	!	
30 minutes	Gas & Wate	т	
	Water		
If bradenhead flowed water, check	all of the descriptions that apply below:		
CLEAR_ FRESH_	SALTY SULFUR B	LACK	
	TOTAL OF THE PROPERTY OF THE PERSON OF THE P	N/A	
5 MINUTE SHUT-IN BRADEN	HEAD INTERMEDIATE		
5 MINUTE SHUT-IN BRADENT REMARKS:	HEAD INTERMEDIATE		
	HEAD_UINTERMEDIATE_Z		
	HEAD_UINTERMEDIATE_Z		