



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION

AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD

AZTEC NM 87410

(505) 334-6178

FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6-30-05 Operator Thompson E&P API # 30-095-07730

Property Name Hartman Well No. 2 Location: Unit Section 3 Township 29N Range 11W

Well Status (Shut-In or Producing) Tubing 4 Intermediate NA Casing 4 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	<u>0</u>	<u>—</u>	<u>4</u>	Steady Flow	
10 minutes	<u>0</u>	<u>—</u>	<u>4</u>	Surges	
15 minutes	<u>0</u>	<u>—</u>	<u>4</u>	Down to Nothing	
20 minutes	<u>0</u>	<u>—</u>	<u>4</u>	Nothing	<u>Nothing</u>
25 minutes	<u>0</u>	<u>—</u>	<u>4</u>	Gas	
30 minutes	<u>0</u>	<u>—</u>	<u>4</u>	Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE NA

REMARKS:

There is a hole between in tubing waiting on rig.
Had to dig up B/H and plumbed above ground.

By L. H. Reid Witness

Pumper
(Position)

E-mail address

