



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION

AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD

AZTEC NM 87410

(505) 334-6170

FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6-30-05 Operator Thompson E&P API # 30-045 23686
Property Name Hartman Well No. 12 Location: Unit 29N Section 31 Township 29N Range 11W
Well Status (Shut-In or Producing) Producing Tubing 8 Intermediate 1A Casing 12 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	0	1	12	Steady Flow	
10 minutes	0	X	12	Surges	
15 minutes	0	1	12	Down to Nothing	
20 minutes	0	1	12	Nothing	Nothing
25 minutes	0	1	12	Gas	
30 minutes	0	1	12	Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE 1A

REMARKS:

Closed B/H 1 week ago - opened to a very slight blow (or suck) that lasted less than a second. This well is pumped up the tubing and produced up the casing.

By Sy H Reid

Witness _____

Purple
(Position)

E-mail address _____

