

## NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION

AZTEC DISTRICT/OFFICE (\*\*)

1000 RIO BRAZOS ROAD

AZTEC NM 87410

(505) 334-6178

FAX: (605) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

## **BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Well Status Shut-In or Producing) Tub OPEN BRADENHEAD AND INTERME				
PRESSURES: TIME <u>BRADENHEAD INTERMEDIATE</u>	CASING		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes 0 NON E	Ø	Steady Flow		
10 minutes		Surges		
15 minutes		Down to Nothing	3	
20 minutes	Ø	Nothing $\sqrt{}$	<del></del>	NONE
25 minutes		Gas		
30 minutes		Gas & Water	·	
		Water		
If bradenhead flowed water, check all of the descriptions that apply below:				
CLEAR FRESH SA	ALTYS	ULFUR BLAC	K	
5 MINUTE SHUT-IN BRADENHEAD	I	NTERMEDIATE		
REMARKS:				
			,	The state of the s
34 Ark Suliver		Witness		
Pumper (Position)			· · · · · · · · · · · · · · · · · · ·	
3-mail address				