## **Deviation Report** Name of Company Address Burlington Resources Oil & Gas Company P.O. Box 4289, Farmington, NM 87499 Lease Name and Number (API Number) Location Sec. Twn. Rge. SAN JUAN 30-6 UNIT #99B (30-039-27695)

(OH)

1550 FNL -180 FWL

County

**RIO ARRIBA** 

Depth (ft)	Deviation (degrees)
60	1.00
120	1.00
611	2.00
954	3.00
1,203	2.75
1,486	2.50
1,771	2.00
2,084	3.00
2,458	2.00
2,706	1.75
2,959	1.50
3,268	0.75
3,407	0.75
7,650	1.00



34-030N-007W

**NEW MEXICO** 

State

Air Hammer Used? YES

**Pool and Formation** 

BLANCO MESAVERDE/BASIN DAKOTA

I, the undersigned, certify that I, acting in my capacity as Petroleum Engineer for Burlington Resources Oil & Gas Company, am authorized by said Company to make this report; and that this report was prepared under my supervision and directions, and that the facts stated herein are true to the best of my knowledge and belief.

Subscribed and sworn to before me this 22nd day of August, 2005.

Notary Public in and for San Juan County, New/Mexico

My commission expires April 5th, 2009.