

Submit 3 Copies To Appropriate District	State of New Mexico		Form C-103	
Office District I	Energy, Minerals and Natural Resources		May 27, 2004	
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.	
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-045- 33 / / / 5. Indicate Type of Lease	
District III	1220 South St. Fran	cis Dr.	STATE FEE	n
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505		6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM	Francis Dr., Santa Fe, NM			
87505 SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreeme	ent Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			Barnes LS	110 1 141110
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			(BLM SF - 078039)	
1. Type of Well: Oil Well Gas Well Other			8. Well Number	
			1 N	
			9. OGRID Number 000778	
BP AMERICA PRODUCTION COMPANY 3. Address of Operator			10. Pool name or Wildcat	
P.O. BOX 3092 HOUSTON, TX 77079-2064			Basin Dakota & Blanco Mesaverde	
4. Well Location				
}	860 feet from the North	line and 1535	feet from the East line	
Section 24	_	Range 11W	T	County
	11. Elevation (Show whether DR,		4214 Treatment of the Contract	County
6215' GR				
Pit or Below-grade Tank Application 🛛 o	r Closure 🗌			
Pit typeDRILLINGDepth to Ground	lwater <u>>100'</u> Distance from nearest fresh	water well <u>> 1000'</u> D	istance from nearest surface water <u> > 10</u>	<u>)00'</u>
Pit Liner Thickness: 12 mil Below-Grade Tank: Volumebbls; Construction Material				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF IN			EQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRIL			<u> </u>	
			LING OPNS. ☐ P AND A	
- PACE ON VELEW CASING	MOCHECONNEC - 10 Teles (2003)	⊕CASING/CEIVIEN I	JOB	
OTHER: LINED DRILLING PIT		OTHER:		· 🗖
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date				
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion				
or recompletion.				
Construct a lined drilling pit per I	3P America – San Juan Basin Dril	ling/ Workover Pit	Construction Plan issued date	of
11/17/2004. Pit will be closed acco		s	6789	700
			\$50.10	11/2
			(3) A S	
			To de se se	2
			O CONTRACTOR	05
			E ON CO.	o j
			(20)	1200
I handky coutify that the information	abana ia 4maa and a mada 4. 4. 4. 4. 1.		25.55.65	La Car
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan.				
\bigcap		s, a general per mit	an (attached) afternative OCD-appio	veu pian .
SIGNATURE (NUM)	TITLE_	Regulatory Analyst	DATE <u>05/20/2005</u> 9-8	1-05
Type or print name Characterist	E mail address: Mass 101		Talankan N. 201 255 12	201
Type or print name Cherry Hlava For State Use Only	E-mail address: hlavacl@bp	.com	Telephone No. 281-366-40	<u>/81</u>
The state of the s	4 2 1	UTY OR & GAS INS	ATTOR DOCT AND COT	mar 6 t C
APPROVED BY:	TITLE	TIE WILL OF WITH HERE	DATE	r Lakou.
Conditions of Approval (if any):	/ /			

PAD LAYOUT PLAN & PROFILE BP AMERICA PRODUCTION COMPANY Barnes LS # 1N 860' F/NL 1535' F/EL

860' F/NL 1535' F/EL SEC. 24, T32N, R11W, N.M.P.M. SAN JUAN COUNTY, NEW MEXICO Lat: 36.9753° Long: 107.9378°

Lat: 36°58'31" Long: 107°56'16"





NOTE: Contractor should call One-Call for location of any marked or unmarked buried pipelines or cables on well pad and/or access road at least two (2) working days prior to construction.

Cuts and fills shown are approximate – final finished elevation is to be adjusted so earthwork will balance. Corner stakes are approximate and do not include additional areas needed for sidestopes and drainages. Final Pad Dimensions are to be verified by Contractor.

VANN SURVEYS P. O. Box 1306 Farmington, NM