



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

RCVD SEP 19 '12

OIL CONS. DIV.

DIST. 3

Date of Test 9-19-12 Operator Chevron API #30-0 39-24562

Property Name Rincon unit Well No. 257 Location: Unit 6 Section 16 Township 27 Range 6

Well Status (~~Shut-In~~ or Producing) Initial PSI: Tubing 36 Intermediate - Casing 37 Bradenhead 39

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM	
	Bradenhead BH	Int	Csg	Int	Csg
5 min	0	-	37		
10 min	0	-	37		
15 min	0	-	37		
20 min	0	-	37		
25 min	0	-	36		
30 min	0	-	36		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	✓
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE -

REMARKS:

Bradenhead down to nothing in 1 1/2 min.

By Randy Calder
Calder service
(Position)

Witness Paul Wike

E-mail address Randy.ac@calderservice.com