

## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/District II//3distric.htm

> Oil Cons. Div District III

## **BRADENHEAD TEST REPORT**

(submit 1 copy to above address)

AUG 1 4 2012

Date of Test 8-8-2012 Operator Black HillS API #30-03929316	
	Location: Unit Section/7 Township 29N Range 02
	Subing 56 Intermediate Casing 19.4 Bradenhead
	TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH
PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
TIME 5 min 0 /9. 4	Steady Flow
10 min 0 21.4	Surges
15 min 0 22	Down to Nothing
20 min	Nothing
25 min	Gas
30 min	Gas & Water
- Water	
If bradenhead flowed water, check all of the descriptions that apply below:	
CLEAR FRESH SALTY SULFUR BLACK	
5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE	
REMARKS: nothing on Braden head, Put compressor in Bipass-	
By Judson Valder	Witness
By Judson Vallet Witness Witness	
E-mail address	

